



Inspection Report

Inspection Date: 2026/05/19

Excavators

General Information

#ERROR!	KUBOTA		
Model Number	U-17-3A		
Year	2025		
Hour (h)	56	Meter	Working
Serial Number	KBCAZ24ATS3E55093		

Options

- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		500		

Note for External Appearance



Undercarriage


Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	230	230
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- The width between the shoes is adjustable




Engine

Model	D902
Serial Number	4SH1022
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component

- Master key and spare key are included



Note for Engine



Admin No. 3000084978