



Inspection Report


Inspection Date: 2018/07/10

Excavators


General Information			
Maker	KOBELCO		
Model Number	SK50UR-3		
Year	2007		
Hour (h)	5358	Meter	Working
Serial Number	YJ06-09161		


Options	
- CAB	- Air conditioner
- Multilever	
- Blade	
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		640		


Note for External Appearance


Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	NG
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure


Note for Undercarriage
The shoe links are loose


Engine	
Model	
Serial Number	A4917
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component


Note for Engine


Admin No. 2018070053