



# Inspection Report

Inspection Date: 2024/10/19

## Excavators

### General Information

|                      |        |              |         |
|----------------------|--------|--------------|---------|
| <b>Maker</b>         | YANMAR |              |         |
| <b>Model Number</b>  | B4-6A  |              |         |
| <b>Year</b>          | 2015   |              |         |
| <b>Hour (h)</b>      | 2853   | <b>Meter</b> | Working |
| <b>Serial Number</b> | 66525  |              |         |

### Options


|              |                 |
|--------------|-----------------|
| - CAB        | - Speed changer |
| - Multilever |                 |
| - Blade      |                 |
| - Arm Crane  |                 |

### Upper Structure

|                  |       | Cylinder |              | Play  |
|------------------|-------|----------|--------------|-------|
|                  |       | Oil Leak | Scratch/Rust |       |
| Boom             | Left  | No       | No           | Small |
|                  | Right | N/A      | N/A          |       |
| Arm              |       | No       | No           | Small |
| Bucket           |       | No       | No           | Small |
| Bucket Size (mm) | 520   |          |              |       |

### Note for External Appearance

- The body has some scratches and rust



### Undercarriage


| <b>Shoe Type</b>    | Steel shoes with rubber pads |      |       |
|---------------------|------------------------------|------|-------|
| <b>Swing Circle</b> | No oil leak                  |      |       |
|                     |                              | Left | Right |
| Shoe Width (mm)     | 350                          | 350  |       |
| Idler               | OK                           | OK   |       |
| Sprocket            | OK                           | OK   |       |
| Pin Bush            | OK                           | OK   |       |
| Upper Roller        | OK                           | OK   |       |
| Track Roller        | OK                           | OK   |       |
| Shoe Link           | OK                           | OK   |       |

### Note for Upper Structure



### Note for Undercarriage

- The undercarriage is rusty  
- The rubber pads are deteriorated



### Engine

|                         |               |
|-------------------------|---------------|
| <b>Model</b>            |               |
| <b>Serial Number</b>    |               |
| <b>Engine Oil Leak</b>  | No oil leak   |
| <b>Engine Oil Gauge</b> | OK            |
| <b>Radiator</b>         | OK            |
| <b>Exhaust Color</b>    | Normal        |
| <b>Blow-by</b>          | No            |
| <b>Engine Sound</b>     | OK            |
| <b>Hydraulic Pump</b>   | No oil leak   |
| <b>Water Pump</b>       | No water leak |
| <b>Oil Cooler</b>       | No oil leak   |
| <b>Motor</b>            | No oil leak   |
| <b>Multi Lever</b>      | No oil leak   |

### Note for Operating Component



### Note for Engine



Admin No. 3000065123