



Inspection Report

Inspection Date: 2022/08/31


Excavators

General Information			
Maker	HITACHI		
Model Number	ZX30UR-3		
Year	2014		
Hour (h)	1728	Meter	Working
Serial Number	HCM1YE00K00036298		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		450		

Note for External Appearance
- The right side cover won't open



Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- The bucket side cutters are missing
- The arm has been reinforced




Note for Undercarriage



Engine	
Model	3TNV88-BSHB
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000042439