



# Inspection Report

Inspection Date:

## Aerial Work Platform

### General Information

|                      |        |
|----------------------|--------|
| <b>Maker</b>         | AICHI  |
| <b>Model Number</b>  | SV04B  |
| <b>Year</b>          | 2006   |
| <b>Hour (h)</b>      |        |
| <b>Serial Number</b> | 702177 |

### Engine

|                         |      |
|-------------------------|------|
| <b>Model</b>            |      |
| <b>Serial Number</b>    |      |
| <b>Engine Oil Leak</b>  | #N/A |
| <b>Engine Oil Gauge</b> | #N/A |
| <b>Exhaust Color</b>    | #N/A |
| <b>Blow-by</b>          | #N/A |
| <b>Engine Sound</b>     | #N/A |
| <b>Radiator</b>         | #N/A |
| <b>Water Pump</b>       | #N/A |
| <b>Injection Pump</b>   | #N/A |

### Note for External Appearance

- The handrail of the platform is detached

### Note for Control Panel

### Note for Engine

- Battery type

### Other Information

- Some parts are missing
- No key
- Operation is unchecked
- Hour is unknown

Admin. No. 3000045976

\*This report is only for your reference. We are not responsible for the actual condition of checked item.