



Inspection Report

Inspection Date: 2026/10/09

Excavators

General Information

Maker	HITACHI		
Model Number	ZX30U-5B		
Year	2020		
Hour (h)	3110	Meter	Working
Serial Number	HCMADHA0H00055535		

Options

- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	No	No	
Arm		Oil oozing	No	Small
Bucket		Oil oozing	No	Small
Bucket Size (mm)		540		

Note for External Appearance

- The body has scratches and rust
- The covers are dented and distorted
- The engraved chassis number (VIN stamp) is unclear



Note for Upper Structure



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Undercarriage

- The rubber shoes are deteriorated



Engine

Model	3TNV88-EPHB
Serial Number	169079
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000090455

*This report is only for your reference. We are not responsible for the actual condition of checked item.