



Inspection Report


Inspection Date: 2018/04/13

Excavators


| General Information | | | |
|----------------------|------------|--------------|---------|
| Maker | KOBELCO | | |
| Model Number | SK200-8 | | |
| Year | 2008 | | |
| Hour (h) | 7045 | Meter | Working |
| Serial Number | YN11-50762 | | |


| Options | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |
| | - Pipings |
| - Arm Crane | |
| - EPA | |

| Upper Structure | | | | |
|------------------|-------|----------|--------------|------|
| | | Cylinder | | Play |
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | No |
| | Right | No | No | |
| Arm | | No | No | No |
| Bucket | | No | No | Big |
| Bucket Size (mm) | | 1030 | | |


| Note for External Appearance |
|---|
|  |

| Undercarriage | | |
|------------------------|-------------|--------------|
| Shoe Type | Steel | |
| Swing Circle | No oil leak | |
| | Left | Right |
| Shoe Width (mm) | 600 | 600 |
| Idler | OK | OK |
| Sprocket | OK | OK |
| Pin Bush | OK | OK |
| Upper Roller | OK | OK |
| Track Roller | OK | OK |
| Shoe Link | OK | OK |

| Note for Upper Structure |
|---|
|  |

| Note for Undercarriage |
|---|
|  |

| Engine | |
|-------------------------|---------------|
| Model | EA-J05E-TA |
| Serial Number | J05E TA18364 |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |

| Note for Operating Component |
|---|
| The seat is partly torn |
|  |

| Note for Engine |
|---|
|  |

Admin No. 2018040345