Inspection Report

Inspection Date: 2026/10/31

Excavators

General Information

Maker	KOMATSU		
Model Number	PC09-1		
Year			
Hour (h)	727	**Meter**	Working
Serial Number	KMTPC0003C04014121		

Options

	- Speed changer
- Blade	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	**Left**	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		320		

Note for External Appearance

- The body has scratches and rust



Note for Upper Structure



Undercarriage

	Left	Right
Shoe Type	Rubber	
Swing Circle	No oil leak	
Shoe Width (mm)	180	180
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Undercarriage



Engine

Model	3D76E-5NBA
Serial Number	02601
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Operating Component



Note for Engine



Admin No. 3000091057

*This report is only for your reference. We are not responsible for the actual condition of checked item.