



Inspection Report


Inspection Date: 2019/03/15

Excavators


General Information			
Maker	KOBELCO		
Model Number	SK115SR-1ES		
Year	2007		
Hour (h)	6540	Meter	Working
Serial Number	YV04-04165		


Options	
- CNP	
- Multilever	
- Blade	
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		830		


Note for External Appearance



Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	500	500	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure


Note for Undercarriage


Engine	
Model	BB-4BG1T
Serial Number	4BG1-951754
Engine Oil Leak	No oil leak
Engine Oil Gauge	Not enough cooling water
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	Water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component


Note for Engine
The water pump is broken


Admin No. 2019030198