



Inspection Report

Inspection Date: 2017/05/06

Excavators

General Information

Maker	KUBOTA		
Model Number	U-40-3S		
Year	2006		
Hour (h)	1808	Meter	Working
Serial Number	308**		

Options

- | | |
|--------------|-------------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | - Breaker Pipings |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	550			

Note for External Appearance

Repainted



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

The rubber pads have cracks and scratches



Shoe Link

Model	V2203KA
Serial Number	06E7717
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component

Torn sheet



Note for Engine



Admin No. 2017040066