



Inspection Report

Inspection Date: 2019/03/26

Excavators

General Information

Maker	KOBELCO		
Model Number	SK75UR-3ES		
Year	2007		
Hour (h)	5158	Meter	Working
Serial Number	YR07-07296		

Options

- CAB	
- Multilever	- Air conditioner
- Blade	
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)	670			

Note for External Appearance



Note for Upper Structure

The blade has some dents



Undercarriage

Shoe Type	Steel shoes with rubber pads			
Swing Circle	No oil leak			
		Left	Right	
Shoe Width (mm)	450	450		
Idler	OK	OK		
Sprocket	OK	OK		
Pin Bush	OK	OK		
Upper Roller	OK	OK		
Track Roller	OK	OK		
Shoe Link	OK	OK		

Note for Undercarriage

Oil oozing from around the swivel



Engine

Model	CC-4JG1PYA-01
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

The seat is partly torn



Note for Engine



Admin No. 2019030438