



Inspection Report

Inspection Date: 2021/05/20

Excavators

General Information

Maker	KOMATSU		
Model Number	PC78US-8		
Year	2013		
Hour (h)	2985	Meter	Working
Serial Number	19700		

Options

- | | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |
| - Blade | - Pippings |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)				

Note for External Appearance

- The side covers are damaged and have some dents
- The body is partly damaged and rusty



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	NG
Shoe Link	OK	OK

Note for Upper Structure

- A standard bucket, slope bucket, and fork claw are included



Note for Undercarriage

- One of the lower rollers has been detached



Engine

Model	SAA4D95LE-5
Serial Number	538636
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	Oil oozing

Note for Operating Component



Note for Engine



Admin No. 3000031504