



Inspection Report

Inspection Date: 2021/05/07

Excavators

General Information

Maker	KOMATSU		
Model Number	PC78US-8		
Year	2011		
Hour (h)	5245	Meter	Working
Serial Number	KMTPC213A01016742		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	- Piping
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		640		

Note for External Appearance

- The front guard has been installed; it's partly deformed
- The right cover is partly damaged
- The lower part of the left cover has some dents
- The step is partly deformed



Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- 5 hydraulic hoses have been installed
- The winch has been installed on the boom
- 4 sides of the arm have been reinforced



Note for Undercarriage



Engine

Model	SAA4D95LE-5-C
Serial Number	517057
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- ROPS (rollover protective structure)



Note for Engine

- Oil oozing from the control valve



Admin No. 3000031394