



# Inspection Report

Inspection Date: 2018/05/29


## Excavators

General Information			
Maker	YANMAR		
Model Number	Vio40-5		
Year	2007		
Hour (h)	5258	Meter	Working
Serial Number	52013B		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Pipings


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil leak	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		570		

Note for External Appearance
- No rear-view mirror - The canopy has some dents - The working lights are partly cracked




Undercarriage		
Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	350	350
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
The bucket has a hole




Note for Undercarriage




Engine	
Model	4TNV88-P
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
The seat is partly torn



Note for Engine
Oil oozing from the hydraulic pump



Admin No. 2018050704