



Inspection Report

Inspection Date: 2026/07/03

Wheel Loader

General Information

Maker	KUBOTA
Model Number	R430Z
Year	2014
Hour (h)	2767
Serial Number	R430-22528

Note for External Appearance

- If domestic marine transport is used (Tomakomai Port → Kawasaki Port) via a coastal ferry, an additional washing fee may be charged. This cost will be borne by the purchaser.



Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Note for Upper Structure



Undercarriage

Front Accel	Oil oozing
Rear Accel	Oil oozing

Note for Operating Component

- With heater/ FAN



Engine

Model	D1703
Serial Number	D1703-7ER3378
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Note for Undercarriage

- Tire size: 12.5/70-16 6P.R.



Documents

Automobile Inspection Certificate	No
-----------------------------------	----

Note for Engine



Admin. No. 3000087915

*This report is only for your reference. We are not responsible for the actual condition of checked item.