



Inspection Report

Inspection Date: 2020/09/04

Excavators

General Information

Maker	KOMATSU		
Model Number	PC78US-5		
Year			
Hour (h)	5906	Meter	Working
Serial Number	1045		

Options

- | | |
|-------|-------------------|
| - CAB | - Speed changer |
| | - Air conditioner |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	Scratch	Small
	Right	Oil oozing	Scratch	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	650			

Note for External Appearance



Undercarriage

Shoe Type	Steel	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage



Engine

Model	4D95LE-2-A
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	Rust/Oil
Exhaust Color	White
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil oozing
Multi Lever	-

Note for Operating Component



Note for Engine

- There are bubbles in the radiator



Admin No. 300015549