



Inspection Report


Inspection Date: 2018/04/13

Excavators


General Information			
Maker	KOBELCO		
Model Number	SK115SR-1ES		
Year	2007		
Hour (h)	3712	Meter	Working
Serial Number	YV04-03930		


Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
	- Pipings
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		Oil oozing	No	Small
Bucket Size (mm)		840		


Note for External Appearance
Partly repainted



Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
- 3 sides of the arm were reinforced
- The inside of the arm has some dents


Note for Undercarriage
The rubber pads are severely worn


Engine	
Model	BB-4BG1T
Serial Number	4BG1-940662
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
The seat is partly torn


Note for Engine
Oil oozing from around the control valve


Admin No. 2018040341