



Inspection Report

Inspection Date: 2018/09/21

Excavators

General Information

Maker	KOMATSU		
Model Number	PC78US-6NO		
Year	2006		
Hour (h)	4892	Meter	Working
Serial Number	9202		

Options

- | | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |
| - Blade | |
| - Arm Crane | |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)	645			

Note for External Appearance

- The engine hood won't open and close properly
- There are some traces of repair on the body



Undercarriage

Shoe Type	Steel shoes with rubber pads		
Swing Circle	Unchecked		
		Left	Right
Shoe Width (mm)	450	450	
Idler	OK	NG	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	NG	NG	

Note for Upper Structure



Note for Undercarriage

- The shoe links are partly loose
- The adjust cylinder is slightly loose



Engine

Model	
Serial Number	
Engine Oil Leak	Unchecked
Engine Oil Gauge	Unchecked
Radiator	Normal
Exhaust Color	Normal
Blow-by	Unchecked
Engine Sound	OK
Hydraulic Pump	Unchecked
Water Pump	Unchecked
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The door has plays
- The left window is not caulked completely



Note for Engine

The engine room is unchecked because the hood won't open



Admin No. 2018090272