



Inspection Report

Inspection Date: 2018/06/15

Excavators

General Information

Maker	YANMAR		
Model Number	B6-5		
Year	2004		
Hour (h)		Meter	#N/A
Serial Number	50842B		

Options

- CNP
- Multilever
- Blade
- Speed changer

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Unchecked
	Right	N/A	N/A	
Arm		No	No	Unchecked
Bucket		No	No	Unchecked
Bucket Size (mm)	790			

Note for External Appearance



Undercarriage

Shoe Type	Rubber	
Swing Circle	Unchecked	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- Oil oozing from the blade cylinder
- The bucket in the picture is not for sale
- Upper structure movement is unchecked



Note for Undercarriage

- The right rubber shoe has deteriorated over time and is partly cracked
- Traveling motion is unchecked



Engine

Model	4TNV88-XBV
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	Rust/Oil
Radiator	Unchecked
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component

- Oil oozing from the left lever
- The seat is partly torn
- The hour meter has been replaced (216h+?)



Note for Engine

Engine movement is unchecked (unable to start)



Admin No. 2018061030