



Inspection Report

Inspection Date: 2022/09/17

Excavators

General Information

Maker	KOMATSU		
Model Number	PC200-8N1		
Year			
Hour (h)	5984	Meter	Working
Serial Number	KMTPC197T02352619		

Options

- | | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |
| | - PIPINGS |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	1030			

Note for External Appearance



Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	600	600
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	NG

Note for Upper Structure

- One of bucket adopters is missing
- The boom has been repaired



Note for Undercarriage

- The right shoe links are worn



Engine

Model	SAA6D107E-1
Serial Number	26587037
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn
- The air conditioner is broken



Note for Engine



Admin No. 3000042422