



Inspection Report


Inspection Date: 2017/10/11

Excavators


General Information			
Maker	KOMATSU		
Model Number	PC20UU-3		
Year	2002		
Hour (h)	3714	Meter	Working
Serial Number	11174		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		415		


Note for External Appearance
Repainted



Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	250	250	
Idler	NG	NG	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure


Note for Undercarriage
The rubber shoes have deteriorated over time


Engine	
Model	3D74E-N3A
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Normal
Blow-by	No
Engine Sound	NG
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	N/A
Multi Lever	No oil leak

Note for Operating Component
- The seat is partly torn
- The roof has some dents


Note for Engine
Abnormal sound from the hydraulic pump (according to the seller)


Admin No. 2017100717