



# Inspection Report

Inspection Date:

#N/A

## General Information

<b>Maker</b>	OHASHI
<b>Model Number</b>	GSC281D
<b>Year</b>	
<b>Hour (h)</b>	531
<b>Serial Number</b>	00150

## Note for External Appearance

- The movement of the engine is checked
- Not checked operation

## Engine

<b>Model</b>	S3L2-EDM2
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	OK
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	Fuel oozing

## Note for Control Panel

## Note for Engine

## Other Information

Admin. No. 3000053647

\*This report is only for your reference. We are not responsible for the actual condition of checked item.