



# Inspection Report

Inspection Date:

## Forklift

### General Information

<b>Maker</b>	UNICARRIESRS
<b>Model Number</b>	XDN-D1F4
<b>Year</b>	2015
<b>Hour (h)</b>	5693
<b>Serial Number</b>	D1F4-10455

### Note for External Appearance

- Repainted
- The covers have rusty and scratches

### Engine

<b>Model</b>	
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	Unchecked
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

### Note for Control Panel

- The side brake lever is deformed

### Note for Engine

### Other Information

Admin. No. 3000080697

\*This report is only for your reference. We are not responsible for the actual condition of checked item.