



Inspection Report

Inspection Date:

Vibrating Roller

General Information

Maker	SAKAI
Model Number	HV60ST
Year	2002
Hour (h)	
Serial Number	VHV12-42319

Note for External Appearance

- Vibrating operation is checked
- Repaint
- The body is rusty and has some scratches
- The engine serial plate is missing

Engine

Model	NFAD6-EKMK
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

Note for Engine

Other Information

Admin. No. 3000062494

*This report is only for your reference. We are not responsible for the actual condition of checked item.