



Inspection Report


Inspection Date: 2018/06/13

Excavators


General Information			
Maker	YANMAR		
Model Number	Vio20-3		
Year	2005		
Hour (h)	2904	Meter	Working
Serial Number	31905B		


Options	
- CNP	- Speed changer
- Blade	- PIPINGS

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)				


Note for External Appearance


Undercarriage		
Shoe Type	Rubber	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	245	245
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure


Note for Undercarriage
Traveling motion is unchecked because there was not an enough space for inspection


Engine	
Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component


Note for Engine


Admin No. 2018060941