



Inspection Report

Inspection Date: 2025/12/11

Excavators

General Information	
Maker	KUBOTA
Model Number	RX-306E
Year	2018
Hour (h)	5577
Meter	Working
Serial Number	24368

Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	

Upper Structure			
		Cylinder	
		Oil Leak	Scratch/Rust
Boom	Left	No	No
	Right	N/A	N/A
Arm	Oil leak	No	Small
Bucket	Oil leak	No	Small
Bucket Size (mm)	300		

Note for External Appearance	
- The VIN plate is damaged	- The body has scratches, rust, and dents
	

Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	NG	NG
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure	
	

Engine	
Model	D1703
Serial Number	7JN3766
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component	
- The seat is torn	- Master key is included
	

Note for Engine	
	

Admin No. 3000079501

*This report is only for your reference. We are not responsible for the actual condition of checked item.