



Inspection Report

Inspection Date: 2024/12/14

Excavators

General Information

Maker	KOMATSU		
Model Number	B3-6A		
Year	2008		
Hour (h)		Meter	Working
Serial Number	62031B		

Options


- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	570			

Note for External Appearance

- Repainted
- The body has some scratches and rust




Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK


Note for Upper Structure

- No bucket side cutters



Note for Undercarriage

- Oil oozing from some left lower rollers




Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- Hour meter is unknown



Note for Engine

--



Admin No. 3000067039