



Inspection Report

Inspection Date: 2018/04/12

Generator

General Information

| | |
|----------------------|-----------|
| Maker | DENYO |
| Model Number | DCA-45ESI |
| Year | 2002 |
| Hour (h) | |
| Serial Number | 3710471 |

Note for External Appearance

Engine

| | |
|-------------------------|---------------|
| Model | BB-4JG1TPD-01 |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Radiator | OK |
| Water Pump | No water leak |
| Injection Pump | No fuel leak |

Note for Control Panel

The hour meter has been replaced (5214h+640h)

Note for Engine

Admin. No. 2018040355

*This report is only for your reference. We are not responsible for the actual condition of checked item.