



Inspection Report


Inspection Date: 2019/02/19

Excavators


General Information			
Maker	YANMAR		
Model Number	SV05		
Year	2008		
Hour (h)	169	Meter	Working
Serial Number	00949B		

Options	
- Multilever	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		280		


Note for External Appearance


Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	150	150	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure


Note for Undercarriage


Engine	
Model	4H3XL
Serial Number	13915
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Unchecked
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	Unchecked

Note for Operating Component
The seat is partly torn


Note for Engine


Admin No. 2019020498