



# Inspection Report

Inspection Date:

#N/A

## General Information

<b>Maker</b>	KOMATSU
<b>Model Number</b>	PW200-1
<b>Year</b>	1990
<b>Hour (h)</b>	0011
<b>Serial Number</b>	10068

## Note for External Appearance

- 2 bucket and bucket pin are missing
- With outrigger
- PIP
- Tires size:10.00-20 14PLY
- HEATER & COOLER

## Engine

<b>Model</b>	S6D105-1
<b>Serial Number</b>	6D105-5591
<b>Engine Oil Leak</b>	Oil oozing
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	OK
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

## Note for Control Panel

## Note for Engine

## Other Information

- This vehicle is temporary deregistered (the document will be delivered after 2 weeks from the sale date.)

Admin. No. 3000053678

\*This report is only for your reference. We are not responsible for the actual condition of checked item.