



Inspection Report

Inspection Date: 2023/09/08

Excavators

General Information

Maker	KOMATSU		
Model Number	PC75UU-2		
Year	1993		
Hour (h)	10006	Meter	Working
Serial Number	6571		

Options


- CAB	
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Big
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)	755			

Note for External Appearance

- The covers are cracked




Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- No bucket side cutters



Note for Undercarriage




Engine

Model	4D95L-1
Serial Number	153135
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	Not enough cooling water
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	-

Note for Operating Component

- The cabin door is missing
- The cabin has some dents
- The window is cracked
- The monitor is cracked
- The seat is torn



Note for Engine



Admin No. 3000052398