



Inspection Report

Inspection Date: 2024/08/08

Wheel Loader

General Information

Maker	HITACHI
Model Number	LX20-7
Year	2005
Hour (h)	4290
Serial Number	HFK4E100E00004526 (F36-04526)

Note for External Appearance

- The cover is rusty and corroded



Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Note for Upper Structure



Undercarriage

Front Accel	Oil oozing
Rear Accel	Oil oozing

Note for Operating Component

- With CAB (cabin) heater



Engine

Model	D1503-DI-K2A
Serial Number	05Q0008
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Note for Undercarriage

- Tire size: 12.5/70-16 6P.R.



Documents

Automobile Inspection Certificate	No
--	----

Note for Engine



Admin. No. 3000062456

*This report is only for your reference. We are not responsible for the actual condition of checked item.