



# Inspection Report

Inspection Date: 2021/05/07

## Motor Grader

### General Information

<b>Maker</b>	KOMATSU
<b>Model Number</b>	GD405A-2
<b>Year</b>	1987
<b>Hour (h)</b>	3371
<b>Serial Number</b>	G40A2-1181

### Note for External Appearance

- CAB type
- A scarifier has been equipped
- 3.1m blade

### Engine

<b>Model</b>	S6D95L
<b>Serial Number</b>	6D95L-33156
<b>Engine Oil Leak</b>	Oil oozing
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	OK
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

### Note for Control Panel

- The seat is partly torn

### Note for Engine

- Oil oozing from the left differential gear of the rear tire

### Other Information

- The vehicle inspection will expire on November 6, 2021

Admin. No. 3000031316

\*This report is only for your reference. We are not responsible for the actual condition of checked item.