



# Inspection Report

Inspection Date: 2019/02/11


## Excavators

General Information			
<b>Maker</b>	SUMITOMO		
<b>Model Number</b>	SH200-6		
<b>Year</b>	2015		
<b>Hour (h)</b>	3490	<b>Meter</b>	Working
<b>Serial Number</b>	SMT200A6C000SC1860		

Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)				

**Note for External Appearance**



Undercarriage		
<b>Shoe Type</b>	Steel	
<b>Swing Circle</b>	No oil leak	
	Left	Right
<b>Shoe Width (mm)</b>	600	600
<b>Idler</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Pin Bush</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Track Roller</b>	OK	OK
<b>Shoe Link</b>	OK	OK

**Note for Upper Structure**  
A standard bucket will be attached before shipment




**Note for Undercarriage**



Engine	
<b>Model</b>	AM-4HK1XZSS-02
<b>Serial Number</b>	4HK1 732650
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

**Note for Operating Component**  
Field-view monitor



**Note for Engine**



Admin No. 2018110205