



Inspection Report

Inspection Date: 2017/08/07

Excavators

General Information			
Maker	KUBOTA		
Model Number	RX-403S		
Year	2005		
Hour (h)	2586	Meter	Working
Serial Number	60139		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		Oil oozing	No	Big
Bucket Size (mm)		550		

Note for External Appearance
Repainted


Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
The dust seal of the bucket cylinder is partly damaged


Note for Undercarriage
Oil oozing from 2 of the lower rollers


Engine	
Model	D1503
Serial Number	05Q0135
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	Oil oozing

Note for Operating Component


Note for Engine


Admin No. 2017080143