

Inspection Report

Inspection Date: 2019/07/10

Excavators

| General Information | | |
|---------------------|------------|---------|
| Maker | KOBELCO | |
| Model Number | SK350D-8 | |
| Year | 2011 | |
| Hour (h) | 6545 Meter | Working |
| Serial Number | LC11-09311 | |

Upper Structure

| | | Cylinder | | Play |
|------------|---------|----------|--------------|------|
| | | Oil Leak | Scratch/Rust | Flay |
| Boom | Left | No | No | No |
| Boom | Right | No | No | NO |
| | Arm | No | No | No |
| | Bucket | No | No | Big |
| Bucket Siz | ze (mm) | 1430 | | |

Undercarriage

| onaoroannago | | |
|-----------------|-------------|-------|
| Shoe Type | Steel | |
| Swing Circle | No oil leak | |
| | Left | Right |
| Shoe Width (mm) | 600 | 600 |
| Idler | ОК | ОК |
| Sprocket | ОК | ОК |
| Pin Bush | ОК | ОК |
| Upper Roller | ОК | ОК |
| Track Roller | ОК | ОК |
| Shoe Link | ОК | ОК |

| Engine | |
|------------------|---------------|
| Model | J08E-TM |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | ОК |
| Radiator | Normal |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | ОК |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |

Options - CAB - Multilever - Air conditioner - Pipings



Note for Upper Structure

| Note for Undercarriage | |
|------------------------|--|
| | |
| | |
| | |
| | |

| Note for Operating Compone | ent |
|----------------------------|-----|
| | |
| | |
| | |
| | |
| Note for Engine | |
| | |
| | |



Admin No.

2019070559

*This report is only for your reference. We are not responsible for the actual condition of checked item.