



Inspection Report

Inspection Date: 2024/05/17


Excavators

General Information			
Maker	YANMAR		
Model Number	ViO30-5B		
Year	2012		
Hour (h)	4867	Meter	Working
Serial Number	55337B		

Options	
- CAB	- Speed changer
- Multilever	
- Blade	
- Arm Crane	
- EPA	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		450		

Note for External Appearance
- Repainted



Undercarriage			
Shoe Type	Rubber		
Swing Circle	Oil oozing		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- With quick hitch




Engine	
Model	3TNV82A-NBV2
Serial Number	96488
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Undercarriage



Note for Operating Component
- The crane monitor is unable to read due to deterioration



Note for Engine



Admin No. 3000057955