



Inspection Report

Inspection Date: 2018/06/15

Excavators

General Information

Maker	YANMAR		
Model Number	ViO20-3		
Year	2006		
Hour (h)	3863	Meter	Working
Serial Number	32976B		

Options


- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		420		

Note for External Appearance

- The body is partly painted
- The canopy has some dents




Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	250	250
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK


Note for Upper Structure

The tip of the arm has some dents



Note for Undercarriage

Oil oozing from the reduction drive of the left travel motor




Engine

Model	3TNV76-P
Serial Number	25268
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component

The seat is partly torn



Note for Engine



Admin No. 2018060921