



# Inspection Report

Inspection Date: 2018/12/05


## Excavators

General Information			
Maker	KUBOTA		
Model Number	U-30-5		
Year			
Hour (h)	1187	Meter	Working
Serial Number	79128		

Options	
- CNP	- Speed changer
- Blade	- Breaker Pipings


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		425		

**Note for External Appearance**  
The engine cover is unstable




Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	NG	OK	
Sprocket	OK	NG	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

**Note for Upper Structure**  
The boom has some plays




**Note for Undercarriage**  
The sprockets are worn



Engine	
Model	7EW3884
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Black/Gray
Exhaust Color	Black/Gray
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

**Note for Operating Component**



**Note for Engine**



Admin No. 2018110336