

Inspection Report

Inspection Date: 2018/12/11

Excavators

General Information			
Maker	YANMAR		
Model Number	Vio30-5B		
Year	2011		
Hour (h)	2965 Meter	Working	
Serial Number	54639B		

Upper Structure

		Cylinder		Play	
		Oil Leak	Scratch/Rust	Flay	
Boom	Left	No	No	No	
Boom	Right	N/A	N/A		
	Arm	No	No	No	
Bucket		No	No	No	
Bucket Size (mm)		470			

Undercarriage

Steel shoes with rubber pads	
No oil leak	
Left	Right
300	300
OK	ОК
OK	ОК
ОК	ОК
	No oil leak Left 300 OK OK OK OK

Engine	
Model	3TNV82A-N
Serial Number	87713
Engine Oil Leak	No oil leak
Engine Oil Gauge	Unchecked
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	ОК
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Options - CNP - Speed changer - Multilever - Blade - Breaker Pipings - EPA

Note for External Appearance

The front light is broken



Note for Upper Structure	

Note for Undercarriage

The rubber pads have deteriorated over time and are worn

Note for Operating Component	
Note for Engine	



Admin No.

*This report is only for your reference. We are not responsible for the actual condition of checked item.