



Inspection Report

Inspection Date: 2022/07/11

Excavators

| General Information | | | |
|---------------------|------------|-------|---------|
| Maker | KOBELCO | | |
| Model Number | SK80UR-6 | | |
| Year | 2014 | | |
| Hour (h) | 4957 | Meter | Working |
| Serial Number | YR10-10386 | | |

| Options | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |
| - Blade | |
| - Arm Crane | |

| Upper Structure | | | | |
|------------------|-------|----------|--------------|-------|
| | | Cylinder | | Play |
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Small |
| | Right | N/A | N/A | |
| Arm | | No | No | Small |
| Bucket | | No | No | Big |
| Bucket Size (mm) | | 680 | | |

| Note for External Appearance |
|---|
|  |

| Undercarriage | | | |
|-----------------|------------------------------|-------|--|
| Shoe Type | Steel shoes with rubber pads | | |
| Swing Circle | No oil leak | | |
| | Left | Right | |
| Shoe Width (mm) | 450 | 450 | |
| Idler | OK | OK | |
| Sprocket | OK | OK | |
| Pin Bush | OK | OK | |
| Upper Roller | OK | OK | |
| Track Roller | OK | OK | |
| Shoe Link | OK | OK | |

| Note for Upper Structure |
|---|
|  |

| Note for Undercarriage |
|---|
| - Oil oozing from 2 left lower rollers |
|  |

| Engine | |
|------------------|----------------|
| Model | AU-4LE2XYSK-01 |
| Serial Number | 4LE-615631 |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |

| Note for Operating Component |
|---|
|  |

| Note for Engine |
|---|
|  |

Admin No. 3000041078