



Inspection Report

Inspection Date: 2018/10/04

Generator

General Information

| | |
|----------------------|------------|
| Maker | DENYO |
| Model Number | DCA-220ESK |
| Year | - |
| Hour (h) | 10281 |
| Serial Number | 3803523 |

Note for External Appearance

Engine

| | |
|-------------------------|---------------|
| Model | SAA6D125E-2-B |
| Serial Number | 211866 |
| Engine Oil Leak | Oil oozing |
| Engine Oil Gauge | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Radiator | OK |
| Water Pump | No water leak |
| Injection Pump | No fuel leak |

Note for Control Panel

Note for Engine

- The dynamo (battery charger) is broken according to the seller
- You need to turn off the emergency switch before you stop the engine

Admin. No. 2018100011

*This report is only for your reference. We are not responsible for the actual condition of checked item.