



Inspection Report

Inspection Date: 2025/12/11

Excavators

General Information

| | | | |
|---------------|-------------------|-------|---------|
| Maker | HITACHI | | |
| Model Number | ZX17U-5A | | |
| Year | 2018 | | |
| Hour (h) | 815 | Meter | Working |
| Serial Number | HCMABAA0T00023962 | | |

Options

| | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | |

Upper Structure

| | | Cylinder | | Play |
|------------------|-------|----------|--------------|-------|
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Small |
| | Right | No | No | |
| Arm | | No | No | Small |
| Bucket | | No | No | Small |
| Bucket Size (mm) | | 400 | | |

Note for External Appearance



Undercarriage

| Shoe Type | Steel shoes with rubber pads | |
|-----------------|------------------------------|-------|
| Swing Circle | No oil leak | |
| | Left | Right |
| Shoe Width (mm) | 230 | 230 |
| Idler | OK | OK |
| Sprocket | OK | OK |
| Pin Bush | OK | OK |
| Upper Roller | OK | OK |
| Track Roller | OK | OK |
| Shoe Link | OK | OK |

Note for Upper Structure



Note for Undercarriage

- The width between the shoes is adjustable



Engine

| | |
|------------------|---------------|
| Model | 3TNV70-PHBB |
| Serial Number | J9591 |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |

Note for Operating Component



Note for Engine



Admin No. 3000079553

*This report is only for your reference. We are not responsible for the actual condition of checked item.