



Inspection Report

Inspection Date:

#N/A

General Information

Maker	ISUZU
Model Number	PDG-NKR85YN
Year	2011
Hour (h)	4153
Serial Number	NKR85Y-7002575

Note for External Appearance

- Upper: AICHI SK17A Serial No.: 734321
- Work platform height: 17.1m
- Tires: Studless 205/80R17.5 120/118L LT
- The truck frame is rusty and corroded

Engine

Model	4JJ1
Serial Number	4JJ1 152545
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

Note for Engine

- Mileage: 92,730km
- F6 transmission

Other Information

Admin. No. 3000084391

*This report is only for your reference. We are not responsible for the actual condition of checked item.