



# Inspection Report

Inspection Date: 6/28/2016

## Excavator

### General Information

Maker	SUMITOMO
Model Number	SH75XU-3
Year	2003
Hour (h)	5611
Serial Number	075[REDACTED]

### Note for External Appearance

Repainted



### Upper Structure

Boom Cylinder (Left)	No oil leak
Boom Cylinder (Right)	No oil leak
Arm Cylinder	No oil leak
Bucket Cylinder	No oil leak
Bucket Width (mm)	なし
Swing	No backlash and play

### Note for Upper Structure

Equipped with offset boom  
There is a backlash in the offset boom



### Undercarriage

Swivel Joint	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

### Note for Undercarriage

Air conditioner not working



### Note for Operating Component



### Engine

Model	4TNE98-SH
Serial Number	26356
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

### Note for Engine

