



Inspection Report

Inspection Date: 2018/06/15

Excavators

General Information

Maker	YANMAR		
Model Number	Vio15-2		
Year	2006		
Hour (h)	2320	Meter	Working
Serial Number	28625B		


Options

- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		500		


Note for External Appearance

- No caution plate	
- The fuel lid is deformed	


Undercarriage

Shoe Type	Rubber	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	230	230
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

The bucket in the picture is not for sale	
---	---


Note for Undercarriage

The rubber shoes have deteriorated over time and are partly worn	
--	---


Engine

Model	3TNV70-W
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil oozing
Multi Lever	No oil leak

Note for Operating Component

- The seat is partly torn	
- The canopy is partly deformed	

Note for Engine

Oil oozing from the hydraulic pump hose	
---	---

Admin No. 2018060838