



Inspection Report

Inspection Date: 2026/07/01

Excavators

General Information

#ERROR!	KUBOTA		
Model Number	U-20-3S		
Year	2013		
Hour (h)	1537	Meter	Working
Serial Number	15763		

Options

- | | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		400		

Note for External Appearance

- Repainted
- Oil oozing from some lower rollers



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	250	250
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage



Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000087380

*This report is only for your reference. We are not responsible for the actual condition of checked item.