



Inspection Report


Inspection Date: 2018/12/08

Excavators


General Information			
Maker	SUMITOMO		
Model Number	SH200-5		
Year	2013		
Hour (h)	4140	Meter	Working
Serial Number	SMT200A5T00SC4346		


Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		1020		


Note for External Appearance



Undercarriage		
Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	600	600
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure


Note for Undercarriage
<ul style="list-style-type: none"> - The cover of the right travel motor is partly deformed - The cover near the left idler is partly deformed - The adjuster of the left shoe is unchecked 

Engine	
Model	AI-4HK1XYSS-01
Serial Number	4HK1-704093
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
Field-view monitor


Note for Engine
Oil oozing from around the multi lever


Admin No. 2018110305