



# Inspection Report

Inspection Date: 2019/07/16

## Excavators

### General Information

<b>Maker</b>	KOBELCO		
<b>Model Number</b>	SK135SR-2		
<b>Year</b>	2012		
<b>Hour (h)</b>	3100	<b>Meter</b>	Working
<b>Serial Number</b>	YY06-17554		

### Options

- |              |                   |
|--------------|-------------------|
| - CAB        | - Speed changer   |
| - Multilever | - Air conditioner |
| - Blade      | - Pippings        |
| - Arm Crane  |                   |

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		890		

### Note for External Appearance

- Repainted
- No arm crane plate



### Undercarriage

<b>Shoe Type</b>	Steel shoes with rubber pads		
<b>Swing Circle</b>	No oil leak		
	<b>Left</b>	<b>Right</b>	
<b>Shoe Width (mm)</b>	500	500	
<b>Idler</b>	OK	OK	
<b>Sprocket</b>	OK	OK	
<b>Pin Bush</b>	OK	OK	
<b>Upper Roller</b>	OK	OK	
<b>Track Roller</b>	OK	OK	
<b>Shoe Link</b>	OK	OK	

### Note for Upper Structure



### Note for Undercarriage



### Engine

<b>Model</b>	D04FR-KDP2TAAC
<b>Serial Number</b>	D04FR-011452
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component



### Note for Engine

The battery is flat and needs to be replaced



Admin No. 2019070478