

# PC40MR-3 Mini Shovel

## BASIC INFORMATION

Inspection Date		Model	PC40MR-3	Serial No.	22437
Date of Manufacture		Hourmeter	2094 HR	Condition of Hourmeter	
Hourmeter (Estimated)		Engine No.		Job Status	Rental
Accident History		Cabin/Canopy	Cabin	Cabin Type	ROPS
Front Attachment	Standard	Type of Shoe	Rubber	Width of Track Shoe	400
Bucket/Attachment	Standard BK	Stamp		Others	

## OPERATION

Engine	Normal	Exhaust Gas Color	Normal	Swing	Normal
Wear: Swing Bearing	Slight	Traveling	Normal	Front Attachment	Normal

## UNDERCARRIAGE/CHASSIS/TIRES

Seize: Track Links	No	Wear: Track Link Extension (Right)	Moderate/Within Service Limit	Wear: Track Link Extension (Left)	Moderate/Within Service Limit
Wear: Track Link Tread(Right)	Slight	Wear: Track Link Tread(Left)	Slight	Wear: Track Link Pins (Right)	Slight
Wear: Track Link Pins (Left)	Slight	Wear: Track Shoe/Rubber Shoe	Moderate/Within Service Limit	Bent/Broken/Missing: Track Shoe	No
Wear: Rubber Pad		Broken/Missing: Rubber Pad		Missing: Rubber Pad	
Broken/Crack: Rubber Shoe(Right)	No	Broken/Crack: Rubber Shoe(Left)	No	Missing: Rubber Shoe Core	No
Wear: Upper Rollers	Slight	Wear: Lower Rollers	Slight	Oil Leak: Rollers	None
Broken/Missing: Rollers	None	Wear: Front Idler(Right)	Slight	Wear: Front Idler(Left)	Slight
Wear: Sprocket(Right)	Slight	Wear: Sprocket(Left)	Slight	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No				

## FRONT & PINS

Boom	Normal	Arm	Normal リペイント	Wear: Boom Foot Pin	Slight
Wear: Boom/Arm Joint Pin	Slight	Wear: Arm Tip Pin	Slight	Wear: Other Pins	Slight
Wear/Deformation: Bucket	Good	Wear/Deformation: Blade	Good		

## OIL/WATER/AIR LEAK

Oil Leak: Front Pipes	No	Oil Leak: Boom Cylinder	No	Oil Leak: Arm Cylinder	No
Oil Leak: Bucket Cylinder	No	Oil Leak: Offset Cylinder	No	Oil Leak: Swing Cylinder	No
Oil Leak: Blade Cylinder	No	Oil Leak: Engine	No	Oil Leak: Oil Cooler	No
Leak: Radiator	No	Leak: Cooling Pipes	No	Oil Leak: Fuel System	No
Oil Leak: Upper Structure	No	Oil Leak: Under Carriage	No	Oil Leak: Pilot Pipes	No
Oil Leak: Pilot Valve	No	Oil Leak: Pump Device	No		

## APPEARANCE

Engine Cover	Good Condition	Side Covers	Good Condition	Under Covers	Good Condition
Counter Weight	Good Condition	Main frame	Good Condition	Track Frame	Good Condition
Cabin/Canopy	Good Condition	Door			

## INTERIOR

Cabin Interior		Seat	Good Condition	Console	Good Condition
Air conditioner		Freon gas inspection			

## OVERALL RATING

Appearance Evaluation	Good	Rust/Corrosion	Slight	Overall Rating	Good
Special Notes	アームはリペイント				